BUY ON
www.cablematic.com

Gigabit USB 3.0 Ethernet Converter

User's Manual

1. Introduction

This Gigabit USB 3.0 Ethernet adapter is a cost effective solution that converts a USB port into a 10/100/1000Base-T Ethernet port. It enables low cost and affordable Gigabit Ethernet network connection to desktop, notebook PC, and embedded system using popular USB ports. No need to purchase an expensive Gigabit network interface card and to spare a PCI or Cardbus slot, just using your existing USB ports and you can upgrade your network connection speed.

2. Features

- Supports 10/100/1000 Mbps auto-sensing capability
- Supports Auto MDIX (straight and cross network cable auto-detection)
- USB specification 1.0, 1.1 and 2.0 and 3.0 compliant
- Supports USB full and high speed modes with bus power capability
- IEEE 802.3, 802.3u, and 802.3ab (10Base-T, 100Base-TX, and 1000Base-T) compatible
- Supports both full-duplex and half-duplex operation in Fast Ethernet
- Supports Jumbo packet of up to 9KB
- Supports suspend mode and remote wakeup via link-up and magic packet

3. System Requirements

- Operating Systems:
  -Windows xp, Windows 7.0, Vista, and Windows 8
  -Mac OS X v10.6 r later
- One available USB port

4. Installing Gigabit USB 3.0 Ethernet Converter (For windows xp/7.0/8.0)

4.1.1 Turn on the power of computer and make sure the USB port is enabled and can working properly.

4.1.2 Insert the driver of Ethernet Adapter into CD-ROM drive.
Select "Install Products –Gigabit USB 3.0 Ethernet Converter - Install".

4.1.3 Double click "setup.exe "then it will start install

AX88179 Windows 7 Drivers - InstallShield Wizard
Preparing to Install...
AX88179 Windows 7 Drivers Setup is preparing the InstallShield Wizard, which will guide you through the program setup process. Please wait.
Preparing to Install...
Cancel

4.1.4 Click on “Finish” to end this installation.


AX88179 Windows 7 Drivers - InstallShield Wizard
InstallShield Wizard Complete
Setup has finished installing AX88179 Windows 7 Drivers on your computer.
< Back
Finish
Cancel

4.1.5 Plug in the USB 3.0 to 10/100/1000 Base-TX Ethernet Adapter into the USB port. Windows will detect an USB Device. Your new hardware is installed and ready to use.



BUY ON
www.cablematic.com

4.1.6 You can to check the Device Manager and see the Network adapters “ASIX AX88179 USB 3.0 to Gigabit Ethernet Adapter ”



BUY ON
www.cablematic.com